RH1280 Change in Propagation Delay
After 1000 Hour Life Test
Tested at 4.5 Volts, 125C